


IES Photometric files RAU


Import the proper Iso-curves into your CAD drawing

Iso curves in footcandles


unit: feet




Mounting 9 feet



Mounting 10 feet



Mounting 11 feet



Mounting 12 feet

